

Event: CFYR97469 **Driver:** Roy J Palmer | **Group:** S03775 - Baltimore Hauling | **Vehicle:** 312132 | **Score:** 0 | **Status:** Resolved

Analysis ▲

Event Trigger:

Outcome:

Details ▲

Recorded Date: 10/16/2017 7:09:15 AM
Downloaded Date: 10/16/2017 12:00:40 PM
Review Date: 12/31/1899 8:00:00 PM
Coach: Unknown User
Last Updated Date: 10/16/2017 12:00:40 PM
Serial Number: ER93A344
Model:

Location ▲

Speed: 0.6 MPH
Coordinates: 39° 19' 37" N -76° -37' 0" W
Heading:

Comments ▲

Comments:

Retention ▲

Default Type ▼

[Set Retention Type](#)

Type Name: Default Type
Duration: 240 months
Expires On: 10/16/2037 4:00:40 PM

Analysis ▲

Event Trigger:
Outcome:

Details ▲

Recorded Date: 10/16/2017 7:12:42 AM
Downloaded Date: 10/16/2017 12:01:02 PM
Review Date: 12/31/1899 8:00:00 PM
Coach: Unknown User
Last Updated Date: 10/16/2017 12:01:01 PM
Serial Number: ER93A344
Model:

Location ▲

Speed: 0.1 MPH
Coordinates: 39° 19' 36" N -76° -37' 0" W
Heading:

Comments ▲

Comments:

Retention ▲

Default Type ▼ [Set Retention Type](#)

Type Name: Default Type
Duration: 240 months
Expires On: 10/16/2037 4:01:02 PM

| event_id | event_status | company_name | group_level_1 | group_level_2 |
|-----------|--------------|------------------|------------------|--------------------|
| CFYR97474 | Resolved | Waste Management | Waste Management | -Waste Management- |
| CFYR97469 | Resolved | Waste Management | Waste Management | -Waste Management- |

WM_00056

| group_level_3 | group_level_4 | group_level_5 |
|---------------|-----------------------|---|
| EAST | K00185 - Capitol Area | C00953 - Washington-Baltimore-NOVA COL WM of MD |
| EAST | K00185 - Capitol Area | C00953 - Washington-Baltimore-NOVA COL WM of MD |

WM_00057

| group_level_6 | group_level_7 | group_level_8 | group_level_9 |
|----------------------------|----------------------------|---------------|---------------|
| MD0016 - Baltimore Hauling | S03775 - Baltimore Hauling | | |
| MD0016 - Baltimore Hauling | S03775 - Baltimore Hauling | | |

WM_00058

| group_level_10 | group_level_11 | group_level_12 | group_level_13 | group_level_14 | group_level_15 |
|----------------|----------------|----------------|----------------|----------------|----------------|
| | | | | | |
| | | | | | |

WM_00059

| group_level_16 | group_level_17 | er_serial_number | vehicle_description | vehicle_type | driver_id |
|----------------|----------------|------------------|---------------------|---------------|-----------|
| | | ER93A344 | 312132 | Loader (rear) | 217262 |
| | | ER93A344 | 312132 | Loader (rear) | 217262 |

WM_00060

| driver_last_name | driver_first_name | driver_full_name | driver_home_group | record_date |
|------------------|-------------------|------------------|----------------------------|-------------|
| Palmer | Roy J | Roy J Palmer | S03775 - Baltimore Hauling | 10/16/2017 |
| Palmer | Roy J | Roy J Palmer | S03775 - Baltimore Hauling | 10/16/2017 |

WM_00061

| record_time | time_zone | record_date_utc | record_year | record_month | record_week | record_day |
|-------------|-----------|-----------------|-------------|--------------|-------------|------------|
| 7:12:42 | EST | 10/16/2017 | 2017 | 10 | 43 | 16 |
| 7:09:15 | EST | 10/16/2017 | 2017 | 10 | 43 | 16 |

WM_00062

| record_day_of_week | record_hour | record_yyyyww | record_yyyymm | latitude | longitude |
|--------------------|-------------|---------------|---------------|-----------|-----------|
| 1 | 7 | 201743 | 201710 | 39.326727 | -76.61686 |
| 1 | 7 | 201743 | 201710 | 39.3272 | -76.61681 |

WM_00063

| event_score | scored_event | event_review_date_time_utc | coachable_event |
|-------------|--------------|----------------------------|-----------------|
| 0 | 0 | | 0 |
| 0 | 0 | | 0 |

WM_00064

| creation_date_time_utc | coaching_overdue_date_time_utc | coached_date_utc | coach_name |
|------------------------|--------------------------------|------------------|------------|
| 10/16/2017 16:01 | | | |
| 10/16/2017 16:00 | | | |

WM_00065

| handheld_device_trigger | no_seat_belt_trigger | food_or_drink_trigger | driver_smoking_trigger |
|-------------------------|----------------------|-----------------------|------------------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00066

| inattentive_trigger | lens_obstruction_trigger | accelerating_all | accelerating_trigger |
|---------------------|--------------------------|------------------|----------------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00067

| cornering_trigger | braking_trigger | rough_uneven_surface_trigger | speeding_all |
|-------------------|-----------------|------------------------------|--------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00068

| speed_policy_trigger | posted_speed_trigger | adas_all | lane_departure_trigger |
|----------------------|----------------------|----------|------------------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00069

| critical_distance_trigger | following_distance_trigger | in_lane_fitness_trigger | rolling_stop_trigger |
|---------------------------|----------------------------|-------------------------|----------------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00070

| roll_stability_trigger | pedestrian_trigger | other_trigger | driver_tagged_trigger |
|------------------------|--------------------|---------------|-----------------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00071

| parked_highway_ramp_trigger | behaviors_all | handheld_device | no_set_belt | food_or_drink |
|-----------------------------|---------------|-----------------|-------------|---------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00072

| driver_smoking | inattentive | suspected_collision | lens_obstruction | near_collision_unavoidable |
|----------------|-------------|---------------------|------------------|----------------------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00073

| near_collision | collision | possible_collision | distraction_all | cellphone_all | cellphone_handheld_all |
|----------------|-----------|--------------------|-----------------|---------------|------------------------|
| 0 | 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 | 0 |

WM_00074

| cellphone_hands_free_all | cell_distraction | cell_handheld_distraction | cell_handheld_observed |
|--------------------------|------------------|---------------------------|------------------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00075

| cell_handfree_distraction | cell_handfree_observed | food_and_drink_all | food_drink_distraction |
|---------------------------|------------------------|--------------------|------------------------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00076

| food_drink_observed | other_communication_device_all | other_communication_device_distract |
|---------------------|--------------------------------|-------------------------------------|
| 0 | 0 | 0 |
| 0 | 0 | 0 |

WM_00077

| other_communication_device_observed | electronic_device_distraction |
|-------------------------------------|-------------------------------|
| 0 | 0 |
| 0 | 0 |

WM_00078

| electronic_device_observed | other_distraction | passenger | awareness_all | late_response |
|----------------------------|-------------------|-----------|---------------|---------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00079

| blank_stare | not_scanning_roadway | intersection_awareness | mirror_use | driver_conduct_all |
|-------------|----------------------|------------------------|------------|--------------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00080

| other_concern | aggressive | positive_recognition | fundamental_all | failed_to_keep_an_out |
|---------------|------------|----------------------|-----------------|-----------------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00081

| too_fast_for_conditions | unsafe_lane_change | following_distance_all |
|-------------------------|--------------------|------------------------|
| 0 | 0 | 0 |
| 0 | 0 | 0 |

WM_00082

| following_distance_lt_1_second | following_distance_1_sec_to_2_sec |
|--------------------------------|-----------------------------------|
| 0 | 0 |
| 0 | 0 |

WM_00083

| following_distance_2_sec_to_3_sec | following_distance_3_sec_to_4_sec | traffic_violation_all |
|-----------------------------------|-----------------------------------|-----------------------|
| 0 | 0 | 0 |
| 0 | 0 | 0 |

WM_00084

| incomplete_stop | failed_to_stop | red_light | not_on_designated_roadway | posted_speed_violation |
|-----------------|----------------|-----------|---------------------------|------------------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00085

| speed_policy_violation | other_violation | driver_condition_all | drowsy | falling_asleep |
|------------------------|-----------------|----------------------|--------|----------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00086

| driver_unbelted_all | roadway | residential_roadway | off_identifiable_roadway | company_premises |
|---------------------|---------|---------------------|--------------------------|------------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00087

| parking_lot | yard | landfill | passenger_unbelted | other_behaviors | smoking | er_obstruction |
|-------------|------|----------|--------------------|-----------------|---------|----------------|
| 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 | 0 | 0 |

WM_00088

| camera_issue | unusual_event | railroad_crossing | u_turn | right_side_driving | teen_driver_unbelted |
|--------------|---------------|-------------------|--------|--------------------|----------------------|
| 0 | 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 | 0 |

WM_00089

| road_conditions | open_laptop | passengers_in_vehicle | passenger_too_far_forward | high_flagging |
|-----------------|-------------|-----------------------|---------------------------|---------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00090

| trailer_detachment | emergency_status | pedestrian_bicyclist | roadway_pick_up | cornering_speed |
|--------------------|------------------|----------------------|-----------------|-----------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00091

| excessive_idling | railroad_crossing_passenger_onboard | backing | passenger_fall | forks_policy |
|------------------|-------------------------------------|---------|----------------|--------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00092

| loose_object_in_cab | loose_object_in_cargo_area | sleeper_berth_securement | rollaway |
|---------------------|----------------------------|--------------------------|----------|
| 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 |

WM_00093

| child_present | unsafe_and_unnecessary | tandem_slide | open_cargo_door | animal_strike |
|---------------|------------------------|--------------|-----------------|---------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 |

WM_00094

| driver_tagged | tree_strike | gate_strike | parked_highway_ramp | rolling_stop | lane_departure |
|---------------|-------------|-------------|---------------------|--------------|----------------|
| 0 | 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 | 0 |

WM_00095

| pedestrian | critical_distance | unbelted_on_tarmac |
|------------|-------------------|--------------------|
| 0 | 0 | 0 |
| 0 | 0 | 0 |

WM_00096